

FIG. 1 PRIOR ART

FIG. 5





FIG. 2

F I G. 3








FIG. 4

Condition			
Sink mark	<input checked="" type="checkbox"/> Flash	Warpage	
Silver	Short	Weld lines	
Quality			
Better	<input checked="" type="checkbox"/> Worse		
<input type="checkbox"/> Setting			

FIG. 6

FIG. 7






FIG. 10